
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-060	Smoke	9/8/2008	ADS/TM	S11AA1019MH	Dry	Yes	558.28

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11AA1011G1	S11AA1011MH	S11AA1019MH	217.1571	8
S11AA1019G1	S11AA1019MH	S13AA1017MH	250.5203	8
S13AA1017G1	S13AA1017MH	S13AA1001MH	90.60532	8

Observations & Photos

Obs_ID S1028-060-OB01

Address 3241 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3241 Dorithan Rd



Picture \S1028-060-OB01-P01.jpg

Comments Front of house, 3241 Dorithan Rd

Obs_ID S1028-060-OB02

Address 3239 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3239 Dorithan Rd



Picture \S1028-060-OB02-P01.jpg

Comments Front of house, 3239 Dorithan Rd

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-060	Smoke	9/8/2008	ADS/TM	S11AA1019MH	Dry	Yes	558.28

Obs_ID S1028-060-OB03

Address 3229 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from clenaout in front yard. 3229 Dorithan Rd



Picture \S1028-060-OB03-P01.jpg

Comments Front of house, 3229 Dorithan Rd

Obs_ID S1028-060-OB05

Address 3213 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1019MH

Comments Smoke from cleanout in front yard. 3213 Dorithan Rd



Picture \S1028-060-OB05-P01.jpg

Comments Front of house, 3213 Dorithan Rd

Obs_ID S1028-060-OB04

Address 3215 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1019MH

Comments Smoke from cleanout in front yard. 3215 Dorithan Rd



Picture \S1028-060-OB04-P01.jpg

Comments Front of house, 3215 Dorithan Rd

Obs_ID S1028-060-OB06

Address 3200 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13AA1017MH

Comments Smoke from cleanout in front yard. 3200 Dorithan Rd



Picture \S1028-060-OB06-P01.jpg

Comments Front of house, 3200 Dorithan Rd

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-060	Smoke	9/8/2008	ADS/TM	S11AA1019MH	Dry	Yes	558.28

Obs_ID S1028-060-OB07

Address 3214 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1019MH

Comments Smoke from cleanout in front yard. 3214 Dorithan Rd



Picture \S1028-060-OB07-P01.jpg

Comments Front of house, 3214 Dorithan Rd

Obs_ID S1028-060-OB09

Address 3218 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1019MH

Comments Smoke from cleanout in front yard. 3218 Dorithan Rd



Picture \S1028-060-OB09-P01.jpg

Comments Front of house, 3218 Dorithan Rd

Obs_ID S1028-060-OB08

Address 3216 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1019MH

Comments Smoke from cleanout in front yard. 3216 Dorithan Rd



Picture \S1028-060-OB08-P01.jpg

Comments Front of house, 3216 Dorithan Rd

Obs_ID S1028-060-OB10

Address 3226 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3226 Dorithan Rd



Picture \S1028-060-OB10-P01.jpg

Comments Front of house, 3226 Dorithan Rd

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-060	Smoke	9/8/2008	ADS/TM	S11AA1019MH	Dry	Yes	558.28

Obs_ID S1028-060-OB11

Address 3228 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke form cleanout in front yard. 3228 Dorithan Rd



Picture \S1028-060-OB11-P01.jpg

Comments Front of house, 3228 Dorithan Rd

Obs_ID S1028-060-OB12

Address 3230 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3230 Dorithan Rd



Picture \S1028-060-OB12-P01.jpg

Comments Front of house, 3230 Dorithan Rd

Obs_ID S1028-060-OB13

Address 3232 Dorithan Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3232 Dorithan Rd



Picture \S1028-060-OB13-P01.jpg

Comments Front of house, 3232 Dorithan Rd

Obs_ID S1028-060-OB14

Address 3234 Dorithan Rd


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11AA1011MH

Comments Smoke from cleanout in front yard. 3234 Dorithan Rd



Picture \S1028-060-OB14-P01.jpg

Comments Front of house, 3234 Dorithan Rd